


Electrical Schematic Diagram

110v/60hz/1ph (No Timer)



Part:	Name	Qty
C1	Start Capacitor	1
C2	Work Capacitor	1
LS	Overload switch	1
CT1	Micro switchKW9	1
CT2	Micro switchKW9	1
SB1	Srop switch CP1-10R-10	1
SB2	Start switch CP1-10G-10	1
KM	Contactor CU-113A1B	1
M	110v/1ph AC motor 1.1KW	1