


Electrical Schematic Diagram 110v/60hz/1ph (No Timer)



Part	Name	Qty
C1	Start Capacitor	1
C2	Work Capacitor	1
LS	Overload switch	1
CT1	Micro switchKW9	1
CT2	Micro switchKW9	1
SB1	Srop switch ZB2BSC54C+ZB2BZ102C	1
SB2	Start switch CP1-10G-10	1
KM	Contactor CU-18 3A1B	1
M	110v/1ph AC motor 1.5W	1